TEXAS
Health and Human Services

Exhibit H

Project Site Conditions Photobook

TEXAS
Health and Human Services

Roof Replacement at Building 511

HHSC Project: 20-122-RSC
Rio Grande State Center

Roof Replacement B511

TEXAS
Health and Human Services

SUMMARY OF SCOPE:

Rio Grande State Center

<u>Buildings 511</u>

- Roof Replacement
- Rain gutter and downspout installation
- Exterior siding replacement (north wall)- Alternate #1
- Replace HVAC Condenser unit support- Alternate #2



Photo Index

- Roof
- Building Exterior

Roof

Views looking northward

Roof

Views looking northward

Roof

View looking northeastward

View looking eastward

Roof



View looking eastward

View looking southward

Roof

Views looking southward

Roof

Views looking southward

Roof

Views looking westward

Roof

Views looking westward

Roof

Southeast corner

Roof

Southwest corner

Building Exterior

Northeast corner of building

Building Exterior

North side of building

Building Exterior

Northwest corner of building

Building Exterior



West side of building

Building Exterior

West side of building

Building Exterior

West side of building

Building Exterior

Southwest corner

Building Exterior

South side of building

Building Exterior

Southeast corner

Building Exterior

Southeast corner

Building Exterior

East side of building

Building Exterior

East side of building

Building Exterior

East side of building

TEXAS
Health and Human Services

Thank you

For questions please contact PCS purchaser Jay Dancer via email at jay.dancer@hhs.texas.gov

Thank you for your interest.